



## Three Phase



**Three Phase**




**Performance Curves**

**50CSH6.4 (1/2HP)**

**Synchronous Speed: 3600 RPM**


**2 inch Discharge**



**50CSH6.75 (1HP)**

**Synchronous Speed: 3600 RPM**


**2 inch Discharge**



**50CSH61.5 (2HP)**


**Synchronous Speed: 3600 RPM**

**2 inch Discharge**



**50CS62.2 50CSH62.2 (3HP) Synchronous Speed: 3600 RPM**


**2 inch Discharge**



**Performance Curves**


**50CS63.7 50CSH63.7 (5HP) Synchronous Speed: 3600 RPM**

**2 inch Discharge**




**80CS62.2 80CSH62.2 (3HP) Synchronous Speed: 3600 RPM**

**3 inch Discharge**



**80CS63.7 80CSH63.7 (5 HP) Synchronous Speed: 3600 RPM**

**3 inch Discharge**



**100CS65.5 (7½ HP)**

**Synchronous Speed: 3600 RPM**

**4 inch Discharge**

