



Three Phase




Three Phase



50CSH6.4 (1/2HP)

Synchronous Speed: 3600 RPM


2 inch Discharge



50CSH6.75 (1HP)

Synchronous Speed: 3600 RPM


2 inch Discharge



50CSH61.5 (2HP)


Synchronous Speed: 3600 RPM

2 inch Discharge



50CS62.2 50CSH62.2 (3HP) Synchronous Speed: 3600 RPM


2 inch Discharge



Performance Curves


50CS63.7 50CSH63.7 (5HP) Synchronous Speed: 3600 RPM

2 inch Discharge




80CS62.2 80CSH62.2 (3HP) Synchronous Speed: 3600 RPM

3 inch Discharge



80CS63.7 80CSH63.7 (5 HP) Synchronous Speed: 3600 RPM

3 inch Discharge



100CS65.5 (7½ HP)

Synchronous Speed: 3600 RPM

4 inch Discharge

