



Three phase




Three phase



**50CVSH6.4 (1/2HP)**

**Synchronous Speed: 3600 RPM**


**2 inch Discharge**



**50CVSH6.75 (1HP)**

**Synchronous Speed: 3600 RPM**


**2 inch Discharge**



**50CVSH61.5 (2HP)**

**Synchronous Speed: 3600 RPM**


**2 inch Discharge**



**80CVSH6.75 (1HP)**

**Synchronous Speed: 3600 RPM**


**3 inch Discharge**



**80CVSH61.5 (2HP)**

**Synchronous Speed: 3600 RPM**

**3 inch Discharge**



**80CVS62.2 80CVSH62.2 (3HP) Synchronous Speed: 3600 RPM**

**3 inch Discharge**

